


July 21, 2020

2200 SERIES BIN FILL CONVEYORS REMOVE TRANSPORT PINS FROM HYDRAULIC HITCH



NOTICE

EQUIPMENT DAMAGE LIKELY
Remove Transport Pins from the
optional Hydraulic Hitch before operation.

The two transport pins must be removed from the optional hydraulic hitch before the hitch cylinder is operated. Extensive damage to the equipment may occur if they are left in place!